TESTPASSPORT

練 習 問 題



高 品 質 な 学 習 リ ソ ー ス

https://www.testpassport.jp

1年間無料アップデート

Exam : **3108**

Title : Avaya Scopia® Solution Implementation and Maintenance Exam

Version : DEMO

1.Which statement describes what is not recommended when setting up a Telepresence room?
A. The telepresence room should have no windows.
B. Avoid using hard or polished materials such as glass or marble for walls and furniture.
C. Loudspeakers can be placed anywhere in the room.
D. The wall colors should be a natural solid color, preferably a Pastel color.
Answer: C

2.When using the XT Executive 240, in which three ways can you configure and control it? (Choose three.)
A. Use the endpoint remote control
B. Use the mouse and keyboard
C. Use the endpoint web interface
D. Use Scopia Desktop Client
Answer: B,C,D

3.Which two statements regarding Scopia XT Executive 240 are correct? (Choose two.)
A. The Scopia XT Executive 240 allows anyone to connect their PC or MAC.
B. The Scopia XT Executive 240 must bepermanentlyconnected to a PC or MAC located in the room.
C. The Scopia XT Executive 240 can be upgraded to have an embedded MCU.
D. The Scopia XT Executive 240 cannot be used as a room system.
Answer: B,C

4.What configuration parameter must be available before setting up the Scopia Desktop Server?
A. Scopia Desktop H.323 ID
B. Scopia Desktop SIP ID
C. Scopia Desktop E.164 ID
D. Scopia Desktop URI ID
Answer: A
Reference:http://www.radvision.jp/support/documentation/SCOPIA_Desktop_AG.pdf(page 23)

5.Reports can be generated based on different devices in the Scopia Management System.
For which two devices can reports be generated? (Choose two.)
A. Audio only calls
B. Endpoints
C. MCUs
D. Meetings
Answer: B,C

6.The Scopia Management software license key is based on, and requires, what information?
A. IP address
B. MAC Address
C. Customer product key
D. Serial number
Answer: D

Reference:http://docs.radvision.com/bundle/xt5000_deployment_guide_3_2/xt1000_ag_config_register_product

7.A technician is preparing to upgrade a Scopia MCU.
When is a new license required?
A. when the update changes one of the first two digits in a version number
B. when the update changes one of the any two digits in a version number
C. when the update changes one of the first three digits in a version number
D. when the update changes the third, fourth and fifth digits in the version number
Answer: A
Reference:http://www.radvision.jp/support/documentation/1uscopiamcu57ug.pdf(page 50)

8.A technician would like to upgrade a PathFinder.
Where must the upgrade software be located to proceed with the update?
A. on a TFTP server
B. on a PC that is attached to the MCU with a serial cable
C. on a PC with Putty emulator software attached to the MCU with a serial cable
D. in the updates directory
Answer: A
Reference:http://downloads.avaya.com/css/P8/documents/100173468(page 70)

9.When upgrading the PathFinder, which two considerations must be taken into account? (Choose two.)
A. The Pathfinder will restart.
B. A backup of the Pathfinder will be created.
C. All Active clients will be disconnected.
D. The IP address of the MCU may change.
Answer: A,C
Reference:http://downloads.avaya.com/css/P8/documents/100173468(page 72)